

**MICROCHIP****PIC18F6585/6680/8585/8680****PIC18F6585/6680/8585/8680 Rev. A1 Silicon Errata**

The PIC18F6585/6680/8585/8680 Rev. A1 parts you have received conform functionally to the Device Data Sheet (DS30491C), except for the anomalies described below. Any Data Sheet Clarification issues related to the PIC18F6585/6680/8585/8680 will be reported in a separate Data Sheet errata. Please check the Microchip web site for any existing issues.

**The following silicon errata apply only to PIC18F6585/6680/8585/8680 devices with these Device/Revision IDs:**

| Part Number | Device ID     | Revision ID |
|-------------|---------------|-------------|
| PIC18F6585  | 0000 1010 011 | 0 0001      |
| PIC18F6680  | 0000 1010 001 | 0 0001      |
| PIC18F8585  | 0000 1010 010 | 0 0001      |
| PIC18F8680  | 0000 1010 000 | 0 0001      |

The Device IDs (DEVID1 and DEVID2) are located at addresses 3FFFFEh:3FFFFFh in the device's configuration space. They are shown in hexadecimal in the format "DEVID2 DEVID1".

All the issues listed here will be addressed in future revisions of the PIC18F6585/6680/8585/8680 silicon.

**1. Module: EUSART**

If the transmitter is left enabled while the module is performing an auto-baud operation, an arbitrary data byte may get transmitted.

**Work around**

Clear TXEN (TXSTA<5>) before any auto-baud operation and set it after auto-baud is complete.

Enable TXEN only when a data byte is to be transmitted. Care must be taken to ensure that the TX pin is pulled high, either through an external resistor, or by making the TX pin an output and writing '1' to it to not disturb the transmit line.

**Date Codes that pertain to this issue:**

All engineering and production devices.

**2. Module: EUSART**

This module may perform incorrect auto-baud calculation if the ABDEN (BAUDCON<0>) bit was set while the receive pin was at a low level.

**Work around**

Wait for the RX pin to go high and then set the ABDEN bit.

**Date Codes that pertain to this issue:**

All engineering and production devices.

**3. Module: EUSART**

In Asynchronous Receiver mode, the EUSART does not load the SPBRGH value after completion of auto-baud.

**Work around**

Do not enable the BRG16 (BAUDCON<3>) bit.

If the BRG16 is in use, ensure that the auto-baud SPBRG value does not exceed the 8-bit value.

**Date Codes that pertain to this issue:**

All engineering and production devices.

**4. Module: EUSART**

The CREN (RCSTA<4>) bit is cleared after every auto-baud operation.

**Work around**

Upon completion of auto-baud, manually set the CREN bit.

**Date Codes that pertain to this issue:**

All engineering and production devices.

**5. Module: CCP2**

CCP2CON<3:0> value of '1110' or '1111' produces incorrect PWM output.

**Work around**

Use CCP2CON<3:0> value of '110x' for PWM mode.

**Date Codes that pertain to this issue:**

All engineering and production devices.

# PIC18F6585/6680/8585/8680

## 6. Module: Enhanced Controller Area Network (ECAN™ Technology)

In Mode 2, the `FIFOEMPTY` bit (COMSTAT<7>) is not automatically cleared upon a FIFO empty condition.

### Work around

Clear `FIFOEMPTY` bit twice after reading any message from FIFO. `FIFOEMPTY` will remain set if FIFO is still not empty.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 7. Module: Enhanced Controller Area Network (ECAN™ Technology)

Bits 7 and 6 in the COMSTAT register are swapped for write operation. As a result, performing an individual set/clear bit operation on bit 6 in the COMSTAT register actually sets/clears bit 7 and vice versa. Note that the read operation will read the correct bit.

### Work around

If individual bit clear operation is required, first make sure that the desired bit is not already cleared. If the bit is set, use the swapped bit position. For example, use `'BCF COMSTAT, 6'` to clear bit 7. If the bit is already cleared, do not clear it again.

If possible, operate on the entire register using `'MOVWF, MOVFF, CLRF'`, etc. instructions.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 8. Module: ADC

A/D conversion does not start if the device is put to Sleep during the auto-acquisition period. As a result, the device will need another wake-up event source to wake-up from Sleep.

### Work around

Do not use the auto-acquisition feature when A/D conversion during Sleep is required.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 9. Module: Core (Instruction Set)

The Decimal Adjust W register instruction, `DAW`, may improperly clear the Carry (C) bit (STATUS<0>) when executed.

### Work around

Test the Carry bit state before executing the `DAW` instruction. If the Carry bit is set, increment the next higher byte to be added using an instruction such as `INCFSZ` (this instruction does not affect any Status flags and will not overflow a BCD nibble). After the `DAW` instruction has been executed, process the Carry bit normally (see Example 1).

### EXAMPLE 1: PROCESSING THE CARRY BIT DURING BCD ADDITIONS

|        |           |                       |
|--------|-----------|-----------------------|
| MOVLW  | 0x80      | ; .80 (BCD)           |
| ADDLW  | 0x80      | ; .80 (BCD)           |
|        |           |                       |
| BTFSC  | STATUS, C | ; test C              |
| INCFSZ | byte2     | ; inc next higher LSB |
| DAW    |           |                       |
| BTFSC  | STATUS, C | ; test C              |
| INCFSZ | byte2     | ; inc next higher LSB |

This is repeated for each `DAW` instruction.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 10. Module: Enhanced Controller Area Network (ECAN™ Technology)

The behavior of the Phase Segment 2 Select bit (SEG2PHTS) in the BRGCON2 register is inverted. As a result, when Phase Segment 2 is less than Phase Segment 1, or IPT, the actual bit rate will not be correct.

### Work around

1. Use SEG2PHTS = 0 for freely programmable and '1' for maximum of Phase Segment 1 or Information Processing Time (IPT), whichever is greater.
2. Select Phase Segment 2 such that it is greater or equal to Phase Segment 1.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 11. Module: Enhanced Controller Area Network (ECAN™ Technology)

Bit ERRIF in the PIR3 register is incorrectly set when a message is received in Mode 2. This may incorrectly indicate an error condition on the bus. When ERRIF is incorrectly set, a sequence of steps must be followed to clear the incorrect ERRIF flag.

### Work around

To determine the correct error state, do the following checks:

1. If any of the COMSTAT<5:0> bits are non-zero, an error condition has occurred.
2. Otherwise, an error did not occur.

To remove the incorrect error state, do the following:

1. Clear FIFOEMPTY bit.
2. Clear ERRIF bit.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 12. Module: EUSART

Bit SENDB in the TXSTA register is not automatically cleared by hardware upon completion of transmission of a Sync Break.

### Work around

Check the TRMT bit in TXSTA. If TRMT bit is set, Break transmission is said to be complete.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 13. Module: External Memory Interface

When performing writes on the external memory interface, a short glitch is present on the  $\overline{\text{LB}}$  and  $\overline{\text{UB}}$  lines. The length of the glitch is proportional to FOSC and may vary with process, voltage and temperature. The glitch occurs well before the WRH signal is asserted and no adverse affect on the operation of the external memory interface has been observed.

### Work around

None.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 14. Module: Core

Certain combinations of code sequence, code placement, VDD, FOSC and temperature may cause a corrupted read of fetched instructions or data. A corrupted instruction fetch will cause the part to execute an incorrect instruction with unpredictable results.

Microchip cannot predict which combinations of these conditions will cause this failure.

If this failure mechanism exists in your system, it should become evident during statistically significant preproduction testing, using your particular code sequence and placement, across multiple date codes. Preproduction testing should exercise all the functions of your application across system variables. Any changes to code should be tested in the same manner prior to being implemented.

### Work around

- Try changing the placement of code within program memory. Examples of code placement changes include:
  - Insert a data word of value FFFFh immediately following any table read instruction
  - Insert a data word of value FFFFh as the first instruction in the destination of a CALL or GOTO
  - Insert a data word of FFFFh at the interrupt vector address(es) (0008h and/or 0018h)
  - Insert a data word of value FFFFh immediately following any RETURN, RETLW, or RETFIE instruction

In each of these instances, the literal data behaves as a NOP instruction when it is executed. Using the actual NOP instruction instead of a literal FFFFh may not have the same results.

After making any of the changes described above, it is necessary that you do statistically significant preproduction testing, using your new code sequence and placement, across multiple date codes. Preproduction testing should exercise all the functions of your application across system variables.

- Contact your nearest Microchip sales office for additional help.

### Date Codes that pertain to this issue:

All engineering and production devices.

# PIC18F6585/6680/8585/8680

## 15. Module: Enhanced Controller Area Network (ECAN™ Technology)

Under specific conditions, the first five bits of a transmitted identifier may not match the value in the Transmit Buffer ID register, TXBnSIDH. The following conditions must exist for the corruption to occur:

- A transmit message must be pending.
- The ECAN module must detect a Start-of-Frame (SOF) in the third bit of interframe space.

### Work around

None.

### Date Codes that pertain to this issue:

All engineering and production devices.

## 16. Module: Enhanced Controller Area Network (ECAN™ Technology)

Under specific conditions, the TXBnSIDH register of the pending message for transmission may be corrupted. The following conditions must exist for this event to occur:

- A transmit message must be pending.
- All of the receive buffers must be full with a received message in the Message Assembly Buffer (MAB).
- A receiver buffer must be made available (RXBnCON<RXFUL> set to '0') at one of the following times:
  - When a Start-Of-Frame (SOF) is recognized on the CAN bus.
  - On the instruction cycle prior to the SOF.

The timing of this event is crucial.

### Work around

Ensure that a receive buffer overflow condition does not occur and/or ensure that a transmit request is not pending if a receive buffer overflow condition does exist.

The pseudo code segment in Example 2 is an example of how to disable a pending transmission. This code is for illustration purposes only.

### Date Codes that pertain to this issue:

All engineering and production devices.

## EXAMPLE 2:

```
If (RXBnOVFL == 1)           // Has an overflow occurred?
{
    If (TXREQ == 1)           // Is a transmission pending?
    {
        TXREQ = 0;           // Clear transmit request
        If (TXABT == 1)       // Store transmission aborted status value
            MyFlag = 1;
    }
}
Temp_RXREG = RXBx;           // Read receive buffer
If (MyFlag)                   // Was previous transmission aborted?
{
    TXREQ = 1;                // Set transmit request
    MyFlag = 0;               // Reset stored transmission aborted status
}
```

## 17. Module: EUSART

The Enhanced Universal Synchronous Asynchronous Receiver Transmitter (EUSART) cannot receive asynchronous data at the four fastest baud rates. This occurs when:

- BRGH (TXSTA<2>) = 1  
and
- BRG16 (BAUDCON<3>) = 1

### **Work around**

Use a slower baud rate or a faster system clock speed.

### **Date Codes that pertain to this issue:**

All engineering and production devices.

# PIC18F6585/6680/8585/8680

---

## REVISION HISTORY

### Rev A Document (7/2003)

First revision of this document, silicon issues 1 through 4 (EUSART), 5 (CCP2), 6 and 7 (ECAN™ Technology), 8 (ADC) and 9 (Core) and data sheet clarification issue 1 (Oscillator) and 2 (MCLRE Bit).

### Rev B Document (9/2003)

Added silicon issue 10 (ECAN™ Technology).

### Rev C Document (12/2003)

Added silicon issue 11 (ECAN™ Technology), 12 (EUSART) and 13 (External Memory Interface).

### Rev D Document (12/2006)

Added silicon issue 14 (Core).

### Rev E Document (8/2007)

Removed data sheet clarifications and retitled document as silicon errata. Added silicon issues 15 and 16 (ECAN™ Technology). Corrected silicon issue titles for ECAN Technology.

### Rev F Document (10/2007)

Added silicon issue 17 (EUSART).

---

**Note the following details of the code protection feature on Microchip devices:**

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

#### **Trademarks**

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, KEELOQ logo, microID, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, rPIC and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AmpLab, FilterLab, Linear Active Thermistor, Migratable Memory, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, PICkit, PICDEM, PICDEM.net, PICLAB, PICtail, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rLAB, Select Mode, Smart Serial, SmartTel, Total Endurance, UNI/O, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2007, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.



Printed on recycled paper.

**QUALITY MANAGEMENT SYSTEM**  
**CERTIFIED BY DNV**  
**== ISO/TS 16949:2002 ==**

*Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*



---

## WORLDWIDE SALES AND SERVICE

---

### AMERICAS

#### Corporate Office

2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://support.microchip.com>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

#### Atlanta

Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

#### Boston

Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

#### Chicago

Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

#### Dallas

Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

#### Detroit

Farmington Hills, MI  
Tel: 248-538-2250  
Fax: 248-538-2260

#### Kokomo

Kokomo, IN  
Tel: 765-864-8360  
Fax: 765-864-8387

#### Los Angeles

Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608

#### Santa Clara

Santa Clara, CA  
Tel: 408-961-6444  
Fax: 408-961-6445

#### Toronto

Mississauga, Ontario,  
Canada  
Tel: 905-673-0699  
Fax: 905-673-6509

### ASIA/PACIFIC

#### Asia Pacific Office

Suites 3707-14, 37th Floor  
Tower 6, The Gateway  
Harbour City, Kowloon  
Hong Kong  
Tel: 852-2401-1200  
Fax: 852-2401-3431

#### Australia - Sydney

Tel: 61-2-9868-6733  
Fax: 61-2-9868-6755

#### China - Beijing

Tel: 86-10-8528-2100  
Fax: 86-10-8528-2104

#### China - Chengdu

Tel: 86-28-8665-5511  
Fax: 86-28-8665-7889

#### China - Fuzhou

Tel: 86-591-8750-3506  
Fax: 86-591-8750-3521

#### China - Hong Kong SAR

Tel: 852-2401-1200  
Fax: 852-2401-3431

#### China - Nanjing

Tel: 86-25-8473-2460  
Fax: 86-25-8473-2470

#### China - Qingdao

Tel: 86-532-8502-7355  
Fax: 86-532-8502-7205

#### China - Shanghai

Tel: 86-21-5407-5533  
Fax: 86-21-5407-5066

#### China - Shenyang

Tel: 86-24-2334-2829  
Fax: 86-24-2334-2393

#### China - Shenzhen

Tel: 86-755-8203-2660  
Fax: 86-755-8203-1760

#### China - Shunde

Tel: 86-757-2839-5507  
Fax: 86-757-2839-5571

#### China - Wuhan

Tel: 86-27-5980-5300  
Fax: 86-27-5980-5118

#### China - Xian

Tel: 86-29-8833-7252  
Fax: 86-29-8833-7256

### ASIA/PACIFIC

#### India - Bangalore

Tel: 91-80-4182-8400  
Fax: 91-80-4182-8422

#### India - New Delhi

Tel: 91-11-4160-8631  
Fax: 91-11-4160-8632

#### India - Pune

Tel: 91-20-2566-1512  
Fax: 91-20-2566-1513

#### Japan - Yokohama

Tel: 81-45-471- 6166  
Fax: 81-45-471-6122

#### Korea - Daegu

Tel: 82-53-744-4301  
Fax: 82-53-744-4302

#### Korea - Seoul

Tel: 82-2-554-7200  
Fax: 82-2-558-5932 or  
82-2-558-5934

#### Malaysia - Kuala Lumpur

Tel: 60-3-6201-9857  
Fax: 60-3-6201-9859

#### Malaysia - Penang

Tel: 60-4-227-8870  
Fax: 60-4-227-4068

#### Philippines - Manila

Tel: 63-2-634-9065  
Fax: 63-2-634-9069

#### Singapore

Tel: 65-6334-8870  
Fax: 65-6334-8850

#### Taiwan - Hsin Chu

Tel: 886-3-572-9526  
Fax: 886-3-572-6459

#### Taiwan - Kaohsiung

Tel: 886-7-536-4818  
Fax: 886-7-536-4803

#### Taiwan - Taipei

Tel: 886-2-2500-6610  
Fax: 886-2-2508-0102

#### Thailand - Bangkok

Tel: 66-2-694-1351  
Fax: 66-2-694-1350

### EUROPE

#### Austria - Wels

Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

#### Denmark - Copenhagen

Tel: 45-4450-2828  
Fax: 45-4485-2829

#### France - Paris

Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

#### Germany - Munich

Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

#### Italy - Milan

Tel: 39-0331-742611  
Fax: 39-0331-466781

#### Netherlands - Drunen

Tel: 31-416-690399  
Fax: 31-416-690340

#### Spain - Madrid

Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

#### UK - Wokingham

Tel: 44-118-921-5869  
Fax: 44-118-921-5820

10/05/07